

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

AC (AutoCAD)

| Function | BR | Abstract | BR detection level |
|--------------|---------------|--|--------------------|
| AC (AutoCAD) | BR10000186981 | Open for dialog in AutoCAD "almost" gets stuck | V5-6R2015 SP3 |
| AC (AutoCAD) | BR10000188642 | Title Block not updated properly on checkin through AC integration | V5-6R2014 SP5 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

AFC - Abaqus for CATIA

| Function | BR | Abstract | BR detection level |
|------------------------|---------------|--|--------------------|
| AFC - Abaqus for CATIA | BR10000186464 | Abaqus for CATIA V5 aborts on executing animation with all occurrences when there are multiple analysis documents with attached output databases open if the analysis document is switched after executing animation for any other analysis document | V5-6R2013 Golden |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

BOM

| Function | BR | Abstract | BR detection level |
|----------|---------------|---|--------------------|
| BOM | BR10000181273 | Std Report doesn't work in V5-6R2015 (objects of classes SmarTeam.Std.Reports.GUI.Windows.* cannot be created). | V5-6R2015 SP2 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CAA - C++ API Documentation Generator

| Function | BR | Abstract | BR detection level |
|---------------------------------------|---------------|--|--------------------|
| CAA - C++ API Documentation Generator | BR10000178931 | LCA unique ID not unique in some cases | V5-6R2013 SP4 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CAA - C++ Interactive Dashboard

| Function | BR | Abstract | BR detection level |
|---------------------------------|---------------|--|--------------------|
| CAA - C++ Interactive Dashboard | BR10000183966 | The position of arrow extremity is not created at the same position as the selection point.(CAA) | V5-6R2012 SP4 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA 2D Layout for 3D Design

| Function | BR | Abstract | BR detection level |
|-------------------------------|---------------|--|--------------------|
| CATIA 2D Layout for 3D Design | BR10000184816 | The contents to show error becomes unclear for Japanese and English CATIA. | V5-6R2014 SP5 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA Assembly Design

| Function | BR | Abstract | BR detection level |
|-----------------------|---------------|---|--------------------|
| CATIA Assembly Design | BR10000109005 | Resolved parts (PartNumber + ".CATPart") are regenerated during synchronization (PartName ".CATPart") | V5R20 SP4 |
| CATIA Assembly Design | BR10000175272 | Error with the description of the Moment of Inertia for calculating this measure | V5-6R2013 SP5 |
| CATIA Assembly Design | BR10000186483 | ASD : COINCIDENCE CONSTRAINT UPDATE FAILS AFTER PARAMETER MODIFICATION | V5-6R2013 SP5 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA Circuit Board Design

| Function | BR | Abstract | BR detection level |
|----------------------------|---------------|---|--------------------|
| CATIA Circuit Board Design | BR10000185013 | Circuit Board Design - Export IDF gives incorrect result for generated IDF file | V5-6R2015 SP2 |
| CATIA Circuit Board Design | BR10000187463 | PCB Export - Modified contour in IDF | V5-6R2014 SP5 |
| CATIA Circuit Board Design | BR10000187496 | Unable to get a PCB Board Pad in batch program | V5-6R2014 Golden |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA DXF Interface

| Function | BR | Abstract | BR detection level |
|---------------------|---------------|--|--------------------|
| CATIA DXF Interface | BR10000183594 | If opening the DWG file, part of the color is not converted correctly. | V5-6R2013 SP5 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA Functional Tolerancing

| Function | BR | Abstract | BR detection level |
|------------------------------|---------------|---|--------------------|
| CATIA Functional Tolerancing | BR10000184109 | FTA: Weird Sections are shown at wrong place. | V5-6R2014 SP4 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA Generative Drafting

| Function | BR | Abstract | BR detection level |
|---------------------------|---------------|---|--------------------|
| CATIA Generative Drafting | BR10000185149 | Drafting: Boundary line is incorrect on view creation. | V5-6R2013 SP5 |
| CATIA Generative Drafting | BR10000186505 | Drafting: Thread is defined incorrectly. | V5-6R2014 Golden |
| CATIA Generative Drafting | BR10000186819 | Drafting: The symbol of point is changed after "Align points" is performed. | V5-6R2015 SP3 |
| CATIA Generative Drafting | BR10000187018 | CATIA abends while using Function "Equidistant Points" in Drawing | V5-6R2014 SP3 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA Generative Shape Design

| Function | BR | Abstract | BR detection level |
|-------------------------------|---------------|---|--------------------|
| CATIA Generative Shape Design | BR10000179319 | The distance between two surface edges can't be joined in spite of 0mm. | V5-6R2015 SP1 |
| CATIA Generative Shape Design | BR10000179828 | GSD: Join cannot be created if CATDUA is executed | V5-6R2013 SP5 |
| CATIA Generative Shape Design | BR10000182457 | Result of "Measure Between" is incorrect. | V5-6R2013 SP5 |
| CATIA Generative Shape Design | BR10000182604 | GSD: If "material" is applied, it becomes impossible to edit "Multi Output (Translate)". | V5-6R2013 SP5 |
| CATIA Generative Shape Design | BR10000182801 | CATBodyTessellator doesn't work if tessellation angle is less than 11.25 degrees. | V5-6R2013 SP5 |
| CATIA Generative Shape Design | BR10000182981 | Incorrect Join surface is generated when the "Simplify the result" option is activated to specific surface | V5-6R2013 SP5 |
| CATIA Generative Shape Design | BR10000184151 | GSD: Surface Curvature Analysis provides incorrect result and flicker | V5-6R2014 SP5 |
| CATIA Generative Shape Design | BR10000184995 | GSD: Variable Offset: The result of variable offset is incorrect | V5-6R2013 SP5 |
| CATIA Generative Shape Design | BR10000185167 | When using the "Coordinate" type in the "Measure between" , "Measure Between" cannot be created in succession | V5-6R2013 SP5 |
| CATIA Generative Shape Design | BR10000185351 | Shape Design: Untrim command does not work with the scenario method in a part | V5-6R2013 SP6 |
| CATIA Generative Shape Design | BR10000185453 | A property panel hides and cannot click the OK button | V5-6R2013 SP5 |
| CATIA Generative Shape Design | BR10000185585 | GSD: ABEND when performing the Split. | V5-6R2012 SP4 |
| CATIA Generative Shape Design | BR10000185604 | GSD: Multiple results are created for line | V5-6R2013 SP5 |
| CATIA Generative Shape Design | BR10000185654 | GSD/Thickness cannot be performed after Material is applied | V5-6R2013 SP5 |
| CATIA Generative Shape Design | BR10000185883 | If "Sew Surface" command is performed, CATIA goes in ABEND | V5-6R2013 SP5 |
| CATIA Generative Shape Design | BR10000186204 | Save warning appears with over-written operation.(Remaining issue from a previous correction) | V5-6R2013 SP5 |
| CATIA Generative Shape Design | BR10000186933 | Shape : a hidden curve smooth in a flattened contour will be unhidden after the stacking has been updated | V5-6R2013 SP4 |
| CATIA Generative Shape Design | BR10000187234 | Measure Between: value changes between measures for same surface. | V5-6R2013 SP5 |
| CATIA Generative Shape Design | BR10000187430 | The Deactivate stop update check box is unchecked. | V5-6R2014 SP4 |
| CATIA Generative Shape Design | BR10000188065 | CAA V5-6R2014(R2013): When highlight the Surface CATIA goes in ABEND | V5-6R2014 SP4 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA Generative Sheetmetal Design

| Function | BR | Abstract | BR detection level |
|------------------------------------|---------------|--|--------------------|
| CATIA Generative Sheetmetal Design | BR10000186474 | Unable to generate sheetmetal unfold view in drawing | V5-6R2013 SP3 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA Healing Assistant

| Function | BR | Abstract | BR detection level |
|-------------------------|---------------|---|--------------------|
| CATIA Healing Assistant | BR10000186486 | Surface Connection Checker does not work correctly with unknown error message | V5-6R2013 SP5 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA IGES Interface

| Function | BR | Abstract | BR detection level |
|----------------------|---------------|--|--------------------|
| CATIA IGES Interface | BR10000185645 | GSD: Wireframe is not saved correctly by IGES format | V5-6R2013 SP5 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA Imagine & Shape

| Function | BR | Abstract | BR detection level |
|-----------------------|---------------|--|--------------------|
| CATIA Imagine & Shape | BR10000188395 | Imagine & Shape - Some vertex cannot be selected at " Multi-View Customization " | V5-6R2014 Golden |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA Interactive Drafting

| Function | BR | Abstract | BR detection level |
|----------------------------|---------------|--|--------------------|
| CATIA Interactive Drafting | BR10000186422 | Incorrect Display of NOA Pattern in 3DLive | V5R21 SP2 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA Knowledge Expert Usage (KE1)

| Function | BR | Abstract | BR detection level |
|------------------------------------|---------------|---|--------------------|
| CATIA Knowledge Expert Usage (KE1) | BR10000183891 | Unable to run certain macros after migration to R24 | V5-6R2014 SP5 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA Knowledge Parameters & Rules

| Function | BR | Abstract | BR detection level |
|------------------------------------|---------------|--|--------------------|
| CATIA Knowledge Parameters & Rules | BR10000185402 | Pattern Feature with unequal spacing in Part is not updated properly when configuration in the design table changed. | V5-6R2014 Golden |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA Part Design

| Function | BR | Abstract | BR detection level |
|-------------------|---------------|--|--------------------|
| CATIA Part Design | BR10000172675 | The Japanese name of "No Canonical Curve" in "Offset" in Sketch is not right | V5-6R2013 SP5 |
| CATIA Part Design | BR10000173178 | Representation of faces near edge was broken | V5-6R2013 SP5 |
| CATIA Part Design | BR10000182684 | Sketch Issue when using the curve offset function | V5-6R2014 SP5 |
| CATIA Part Design | BR10000182822 | Sketch Inversion Issue in sketches brought over from R21 to R24 | V5-6R2014 SP5 |
| CATIA Part Design | BR10000183295 | Sketch tangent curves measure is not consistent | V5-6R2013 SP6 |
| CATIA Part Design | BR10000184492 | PDG:Multipocket operating problem in part design | V5-6R2014 SP5 |
| CATIA Part Design | BR10000184520 | PDG: Error after Split-Operation, two faces at same point are not identical | V5-6R2014 SP1 |
| CATIA Part Design | BR10000184526 | Problem in V5-6R2014SP04HF27 and higher with Performance and available Memory (RAM) if user turns his Model with Mouse | V5-6R2014 SP4 |
| CATIA Part Design | BR10000185002 | PDG:Fillet is created with an unexpected form. | V5-6R2014 SP3 |
| CATIA Part Design | BR10000185363 | CATIA will create a transparent face which a user does not desire. | V5-6R2013 SP5 |
| CATIA Part Design | BR10000186047 | Edge Fillet: one ribbon cannot be performed correctly | V5-6R2014 SP4 |
| CATIA Part Design | BR10000186627 | If Datum Solid is copied by Compasses, a Solid which is a copied basis has its color changed | V5-6R2013 SP5 |
| CATIA Part Design | BR10000186848 | Sketcher - Sketch becomes "Under-Constrained" after being moved | V5-6R2014 SP4 |
| CATIA Part Design | BR10000187257 | Self intersection error appears when sketch is modified. | V5-6R2014 SP5 |
| CATIA Part Design | BR10000187616 | SKETCHER : CONSTRAINT ERROR OCCURS WHEN OFFSET VALUE IS MODIFIED. | V5-6R2013 SP5 |
| CATIA Part Design | BR10000188347 | IGES file from CATPart does not retain color when Opacity is changed | V5-6R2014 SP5 |
| CATIA Part Design | BR10000188588 | Colours disappearing if "copy paste with link" on a body | V5-6R2014 SP6 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA Raceway & Conduit Design

| Function | BR | Abstract | BR detection level |
|--------------------------------|---------------|--|--------------------|
| CATIA Raceway & Conduit Design | BR10000184634 | Conduit design parts placement is not associative with the System Routing run they are placed on | V5-6R2015 Golden |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA Sheetmetal

| Function | BR | Abstract | BR detection level |
|------------------|---------------|--|--------------------|
| CATIA Sheetmetal | BR10000188416 | CATIA Crash during the rotation of the CATpart | V5R21 SP4 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA Tubing Design

| Function | BR | Abstract | BR detection level |
|---------------------|---------------|--|--------------------|
| CATIA Tubing Design | BR10000183615 | Routing of flexible tube from connector to connector depends on the order of selection of the connectors | V5-6R2014 SP4 |
| CATIA Tubing Design | BR10000185166 | Tubing Design - Follow tube guide curves are created in main axis instead of in Sub-Product context | V5-6R2014 SP3 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

CATIA Wire Harness Design

| Function | BR | Abstract | BR detection level |
|---------------------------|---------------|---|--------------------|
| CATIA Wire Harness Design | BR10000180364 | Electrical Harness Bundle does not update when simulating Mechanism | V5-6R2015 SP2 |
| CATIA Wire Harness Design | BR10000185521 | Error during export of wires as CSV | V5-6R2014 SP4 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

Composites parameters

| Function | BR | Abstract | BR detection level |
|-----------------------|---------------|---|--------------------|
| Composites parameters | BR10000185199 | Copy of Composite Parameters results in Rosette with no Axis defined | V5-6R2015 SP2 |
| Composites parameters | BR10000187626 | The Orientations of Composite Parameters is not found in search result. | V5-6R2015 SP2 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

Copy - Cut - Paste

| Function | BR | Abstract | BR detection level |
|--------------------|---------------|--|--------------------|
| Copy - Cut - Paste | BR10000178642 | Copy paste of a specific body with draft to another CATPart not possible | V5-6R2014 SP1 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

DC5 - ENOVIA Designer Central for CATIA V5

| Function | BR | Abstract | BR detection level |
|--|---------------|--|--------------------|
| DC5 - ENOVIA Designer Central for CATIA V5 | BR10000184899 | Derived Output "image_jpg" is not generated for CATParts by ENOVIA V6 Import Utility | V5-6R2014 SP3 |
| DC5 - ENOVIA Designer Central for CATIA V5 | BR10000188067 | Once a file is touched always it is taken into account even if it is excluded. | V5-6R2012 SP4 |
| DC5 - ENOVIA Designer Central for CATIA V5 | BR10000188069 | Even if the file is not allowed to be modified by the user there is no identification on the save dialog | V5-6R2012 SP4 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

DELMIA - 3 Axis Surface Machining

| Function | BR | Abstract | BR detection level |
|-----------------------------------|---------------|--|--------------------|
| DELMIA - 3 Axis Surface Machining | BR10000177336 | Publication Name is missing in the Geometry Analyser | V5-6R2014 SP4 |
| DELMIA - 3 Axis Surface Machining | BR10000185913 | Contour Driven operation: Wrong rework area | V5-6R2014 SP4 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

DELMIA - Advanced Machining

| Function | BR | Abstract | BR detection level |
|-----------------------------|---------------|--|--------------------|
| DELMIA - Advanced Machining | BR10000186950 | Machining - Pocketing - Circular interpolation is missing on last path | V5-6R2015 SP2 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

DELMIA - Device Building

| Function | BR | Abstract | BR detection level |
|--------------------------|---------------|---|--------------------|
| DELMIA - Device Building | BR10000165794 | Signature Calibration / Delta Vector values are no longer active after Define Auxiliary Devices | V5R21 SP4 |
| DELMIA - Device Building | BR10000174773 | Set as Current is not set when kinematics is deleted and created. | V5-6R2014 SP4 |
| DELMIA - Device Building | BR10000181789 | Freeze: If there is no "Fix Part" node, V5 freezes. | V5-6R2013 SP5 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

DELMIA - Device Task Definition

| Function | BR | Abstract | BR detection level |
|---------------------------------|---------------|---|--------------------|
| DELMIA - Device Task Definition | BR10000173242 | Mounted device does not follow robot, DOF lost by Activate / Deactivate | V5-6R2013 Golden |
| DELMIA - Device Task Definition | BR10000186436 | Swept volume performance problem when creating multiple swept volumes | V5-6R2013 SP5 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

DELMIA - Emergent Process Management

| Function | BR | Abstract | BR detection level |
|--------------------------------------|---------------|--|--------------------|
| DELMIA - Emergent Process Management | BR10000184294 | Create Modify Disposition plan fails when there is an EPD assigned to a Step on an Operation that is Complete. | V5-6R2013 SP2 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

DELMIA - Human Measurements Editor

| Function | BR | Abstract | BR detection level |
|------------------------------------|---------------|---|--------------------|
| DELMIA - Human Measurements Editor | BR10000185937 | Un realistic posture and Anthropometric parameters mismatch | V5-6R2014 SP2 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

DELMIA - Lathe Machining

| Function | BR | Abstract | BR detection level |
|--------------------------|---------------|---|--------------------|
| DELMIA - Lathe Machining | BR10000184577 | Error when generating apt source file | V5-6R2014 SP5 |
| DELMIA - Lathe Machining | BR10000185052 | Turning Groove Finish Operation, Toolpath Does Not Follow Geometry. | V5-6R2014 SP5 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

DELMIA - NC Machine Tool Simulation

| Function | BR | Abstract | BR detection level |
|-------------------------------------|---------------|---|--------------------|
| DELMIA - NC Machine Tool Simulation | BR10000183714 | Video Replay hangs. | V5-6R2014 SP5 |
| DELMIA - NC Machine Tool Simulation | BR10000185096 | NC code based Simulation: Issue with Catia Machining function to edit G53-59 offsets / Difference in Number of Axes | V5-6R2014 SP4 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

DELMIA - Operations Execution

| Function | BR | Abstract | BR detection level |
|-------------------------------|---------------|---|--------------------|
| DELMIA - Operations Execution | BR10000180427 | Batching issue - Grid data collected at the batch level not displayed at the batch level. | V5-6R2015 Golden |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

DELMIA - Order Planning

| Function | BR | Abstract | BR detection level |
|-------------------------|---------------|---|--------------------|
| DELMIA - Order Planning | BR10000182172 | Password disappears after removing work center while copying a user | V5-6R2015 Golden |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

DELMIA - Prismatic Machining

| Function | BR | Abstract | BR detection level |
|------------------------------|---------------|---|--------------------|
| DELMIA - Prismatic Machining | BR10000178671 | Profile Contouring Drive Curve is not displayed when part is rotated | V5-6R2013 SP1 |
| DELMIA - Prismatic Machining | BR10000179068 | Machining - Axial operations - Wrong value of the depth of a Thread | V5-6R2014 SP5 |
| DELMIA - Prismatic Machining | BR10000181695 | Prismatic Machining - Profile Contouring In/Out | V5-6R2014 SP4 |
| DELMIA - Prismatic Machining | BR10000184980 | Tool-Positioning noch correct (Milling ok / Drilling not ok) | V5-6R2014 SP4 |
| DELMIA - Prismatic Machining | BR10000185187 | Spindle Speed automatic compute from tooling Feeds & Speeds Visual Basic logic | V5-6R2015 SP2 |
| DELMIA - Prismatic Machining | BR10000186379 | Profile smoothing shows the toolpath smooth but soon as you hit ok it goes away | V5-6R2014 SP5 |
| DELMIA - Prismatic Machining | BR10000186658 | Need to compute drilling twice to get computation to stay | V5-6R2014 SP6 |
| DELMIA - Prismatic Machining | BR10000186773 | Machining - Changed value switch back to the previous value | V5-6R2014 SP6 |
| DELMIA - Prismatic Machining | BR10000187357 | Concentric Milling with Zig Zag is causing material to remain when roughing | V5-6R2014 SP1 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

DELMIA - Structure Manufacturing Preparation

| Function | BR | Abstract | BR detection level |
|--|---------------|---|--------------------|
| DELMIA - Structure Manufacturing Preparation | BR10000177076 | Wrong marking lines | V5-6R2014 SP5 |
| DELMIA - Structure Manufacturing Preparation | BR10000180313 | The orientation of edge preparation for stiffeners and beams can't be modified. | V5-6R2014 SP3 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

DMU Navigator

| Function | BR | Abstract | BR detection level |
|---------------|---------------|---|--------------------|
| DMU Navigator | BR10000186393 | If "SaveAsFrozen" is performed using a large assembly data, CATIA goes in ABEND | V5-6R2013 SP5 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

DMU Space Analysis

| Function | BR | Abstract | BR detection level |
|--------------------|---------------|--|--------------------|
| DMU Space Analysis | BR10000185644 | Clash is not detected even though products are interfered. | V5-6R2013 SP5 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

DMU Synthesis

| Function | BR | Abstract | BR detection level |
|---------------|---------------|--|--------------------|
| DMU Synthesis | BR10000187502 | The position of the swept volume result data is changed. | V5-6R2014 SP4 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

Editor

| Function | BR | Abstract | BR detection level |
|----------|---------------|--|--------------------|
| Editor | BR10000186635 | V5-6R2014 SP6 : SmarTeam.exe is not compiled using LARGEADDRESSAWARE flag. | V5-6R2014 SP6 |
| Editor | BR10000187931 | OnViewer hook does not contain information about directory | V5-6R2015 SP3 |
| Editor | BR10000188791 | "Quick search" started from "Search and link" crashes | V5-6R2014 SP4 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

ENOVIA VPM Administration

| Function | BR | Abstract | BR detection level |
|---------------------------|---------------|---|--------------------|
| ENOVIA VPM Administration | BR10000186642 | EV5ADMIN : Part instances in ENOVIA V5 with missing children are not repaired by ENOVCheckMissingChildren | V5-6R2014 SP3 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

ENOVIAvpm - CV5 Interoperability

| Function | BR | Abstract | BR detection level |
|----------------------------------|---------------|--|--------------------|
| ENOVIAvpm - CV5 Interoperability | BR10000187042 | Impossible to configure ENOVIAvpm FBDI | V5-6R2015 SP3 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

ENOVIA VPM Navigator

| Function | BR | Abstract | BR detection level |
|----------------------|---------------|--|--------------------|
| ENOVIA VPM Navigator | BR10000180278 | It takes much more time for 2D drawing update in Case1 compared to case2 or case3 | V5-6R2014 SP4 |
| ENOVIA VPM Navigator | BR10000185936 | VPMV5NAV: Switching from CATPart (Document window) to CATProduct PS window) takes excessive time if structure contains more than 25 levels | V5-6R2014 SP1 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

ENOVIA VPM Product editor

| Function | BR | Abstract | BR detection level |
|---------------------------|---------------|--|--------------------|
| ENOVIA VPM Product editor | BR10000185815 | Unable to detach mod | V5-6R2014 SP3 |
| ENOVIA VPM Product editor | BR10000186893 | Copy and paste Signoff Action results in error message | V5-6R2015 SP2 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

FileMenu

| Function | BR | Abstract | BR detection level |
|----------|---------------|--|--------------------|
| FileMenu | BR10000185430 | "Click OK to terminate" while loading a document in Specification Tree | V5-6R2014 SP4 |
| FileMenu | BR10000188061 | Save as: OSM-0014 memory error | V5-6R2014 SP4 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

Foundation

| Function | BR | Abstract | BR detection level |
|------------|---------------|--|--------------------|
| Foundation | BR10000187111 | SmarTeam workflow with Items - only first object in e-mail when having several Items within Workflow | V5-6R2014 SP3 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

GPS - Generative Part Structural Analysis

| Function | BR | Abstract | BR detection level |
|---|---------------|--|--------------------|
| GPS - Generative Part Structural Analysis | BR10000185007 | GSP Analysis: If "Update All Meshes" is executed, ABEND will occur | V5-6R2013 SP5 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

Junction lines wizard

| Function | BR | Abstract | BR detection level |
|-----------------------|---------------|---|--------------------|
| Junction lines wizard | BR10000181057 | Junction Line Wizard does not create a required junction line | V5-6R2014 SP3 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

Laser Projection

| Function | BR | Abstract | BR detection level |
|------------------|---------------|---|--------------------|
| Laser Projection | BR10000185312 | CLA: Laser Projection Preview is not abiding by Ply Draping Direction | V5-6R2015 SP2 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

Manufacturing Hub Integration (included in DPM Pro

| Function | BR | Abstract | BR detection level |
|---|---------------|--|--------------------|
| Manufacturing Hub Integration (included in DPM Process & Resource Definition) | BR10000185722 | Crashes of V5 when loading certain lines | V5-6R2014 SP3 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

Plies from virtual stacking

| Function | BR | Abstract | BR detection level |
|-----------------------------|---------------|---|--------------------|
| Plies from virtual stacking | BR10000186274 | Minimum tape length listed as option in Ply Group | V5-6R2015 SP2 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

Ply

| Function | BR | Abstract | BR detection level |
|----------|---------------|---|--------------------|
| Ply | BR10000186448 | Manual Ply creation fails after skin swapping is completed. | V5-6R2015 SP2 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

Print

| Function | BR | Abstract | BR detection level |
|----------|---------------|--|--------------------|
| Print | BR10000186792 | Print: All printers appear in Grouped printers list in print dialog box after re-opening Print dialog box. | V5-6R2013 SP6 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

Product Structure

| Function | BR | Abstract | BR detection level |
|-------------------|---------------|---|--------------------|
| Product Structure | BR10000182787 | CATPart without material when copied to Product has material link in Product window which cannot be delete. | V5-6R2014 SP4 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

Slicing group

| Function | BR | Abstract | BR detection level |
|---------------|---------------|---|--------------------|
| Slicing group | BR10000188266 | Composites - Wrong slicing curves created in Exact mode | V5-6R2015 SP3 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

V55 - ENOVIA VPM V5-V6 CATIA Design Coexistence

| Function | BR | Abstract | BR detection level |
|--|---------------|--|--------------------|
| V55 - ENOVIA VPM V5-V6 CATIA Design Coexistence for VPM V5 | BR10000187121 | Constraints migration through DBDI taking long time - VP5 to 3DEXP | V5-6R2015 SP3 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

Viewer

| Function | BR | Abstract | BR detection level |
|----------|---------------|---|--------------------|
| Viewer | BR10000185403 | AutoVue Viewer hangs SmarTeam when changing the Windows - Size | V5-6R2014 SP4 |
| Viewer | BR10000187718 | SmarTeam Desktop Viewer Stability Issues | V5-6R2014 SP5 |
| Viewer | BR10000187927 | AutoVue 20.2.3 issue with WebEditor which is set as jVueURL = http:// <V5-6R2013SP3, AutoVue20.2.3> | V5-6R2013 SP3 |
| Viewer | BR10000187990 | SmarTeam Desktop Viewer hangs after maximizing the window | V5-6R2014 SP5 |
| Viewer | BR10000188393 | Cannot view the file which has "Special Char" in title in Autovue with http protocol | V5-6R2013 SP3 |
| Viewer | BR10000188782 | Error loading library when using Smarteam Desktop Viewer after eDrawings viewer | V5-6R2014 SP4 |

Closed Issues for :V5-6R2016 SP1

This document lists all closed issues for the current Release

XCAD - MULTICAx Gateway

| Function | BR | Abstract | BR detection level |
|-------------------------|---------------|--|--------------------|
| XCAD - MULTICAx Gateway | BR10000178269 | Face colours failing when run with Interactive SaveAs .Jt but ok when run on command line | V5-6R2013 SP2 |
| XCAD - MULTICAx Gateway | BR10000184934 | JT Import - FTA annotations not displayed when using "Annotations in Specification Tree - Under View/Annotation Plane nodes" | V5-6R2014 SP1 |
| XCAD - MULTICAx Gateway | BR10000185348 | Import of most JT files into CATIA with MultiCAD FTA geometry associations enabled, leads to a crash | V5-6R2015 Golden |